



**Name:** IMGP1725  
**Date:** 17/05/2004 15:10:30  
**Description:** Outbuildings to right hand side elevation



**Name:** IMGP1726  
**Date:** 17/05/2004 15:11:08  
**Description:** Rear elevation, vertical cracking



**Name:** IMGP1727  
**Date:** 17/05/2004 15:12:06  
**Description:** Rear elevation, cracking over kitchen window



**Name:** IMGP1729  
**Date:** 17/05/2004 15:12:42  
**Description:** Rear elevation, kitchen/outhouse