



Name: IMGP1730
Date: 20/05/2004 16:43:02
Description: Rear elevation, distortion to kitchen/outhouse



Name: IMGP1731
Date: 20/05/2004 16:43:09
Description: Cracking at rear left hand corner



Name: IMGP1732
Date: 17/05/2004 15:15:40
Description: Kitchen/outhouse



Name: IMGP1733
Date: 20/05/2004 16:43:30
Description: Left hand elevation, vertical cracking/differential settlement