



Name: IMGP1741

Date: 17/05/2004 15:22:52

Description: Collapsed floor adjacent to chimney breast

Name: IMGP1745

Date: 17/05/2004 15:25:40

Description: Excessive settlement to pantry floor



Name: IMGP1750

Date: 20/05/2004 16:44:28

Description: Differential movement within bathroom



Name: IMGP1751

Date: 20/05/2004 16:45:34

Description: Collapsed bathroom ceiling