A16

3400N

3450N

3250E

3650N

3600N

3200E

ASHTREE LANE

3150E

G2

G3

G4

T1

3.0

9.0

7.0

3.0

9.0

7.0

Existing mounding.

Existing soil mound to be part used in construction and reserved to infill break in bund at future phase.

EXISTING TREES:

No	Species	Height	Condition	Retention
T1	Willow	9m	Poor. Limbs broken and fallen into ditch.	Remove
G2	Willow	12m	Poor. Overgrown pollarded trees.	Remove
G3	Willow	4m	Poor. Sparse growth.	Remove
G4	Willow/ Poplar	12m	Fair. Willows supressing Poplars.	Remove Willows Retain Poplars.

S.H.D.C
Planning & Development
30 JAN 2004
Ref 0122104

Springfields Arena Mounding.

Survey and Tree Condition

For: Springfields Horticultural Society

M1123.01 1:500 PGG Jan 2004

landscape architecture | urban design | environmental planning
northen house ford lane northenden manchester m22 4nq
t: +44(0)161 946 0808 f: +44(0)161 946 0713 e: design@barneswalker.co.uk w: www.barneswalker.co.uk

© This drawing and the works depicted thereon are the copyright of Barnes Walker Partnership and may not be used or reproduced without the written permission

barnes • walker