

Above: Excavated area shown in more detail below. Note rotted out timber battens and top surface of now removed brick enclosure to corner of room, possibly site of former garderobe

Below: Shows excavation of loose fill material in former enclosure down to top surface of brick vault to undercroft, possibly being area of former garderobe chute.



Ayscoughfee Hall Spalding: Room F 13 plate 2
© Anderson and Glenn February 2004