















HISTORICAL PLATES




Historical Plate 1: Spalding House of Correction, 1847. From a watercolour by Hilkiah Burgess.
(Source: Leveritt & Elsdon, 1986)



Historical Plate 2: The Sessions House of 1842-3 (left) and the House of Correction (right), looking southwest across the Sheep Market, n.d. © Spalding Gentlemen's Society



Historical Plate 3: Spalding Prison in the early 1880s, looking southwest across the Sheep Market, (Leveritt and Elsdon, 1986)



Historical Plate 4: The Sessions House (left), houses in Victoria Street (centre) and the former Drill Hall (right), looking southwest across the Sheep Market, c.1920 ©



Historical Plate 5: The Regent Cinema, looking west across the Sheep Market, n.d. © Heritage South Holland.



Historical Plate 6: Aerial Photograph of the Site in 1930 showing the Regent Cinema and the Sheep Market, looking east © Historic England EPW031856



Historical Plate 7: Aerial Photograph of the Site in 1930 showing the Regent Cinema and the Sheep Market, looking north-east © Historic England EPW031855



Historical Plate 8: Aerial Photograph of the Site in 1930 showing the Regent Cinema and the Sheep Market, looking north-east © Historic England EPW031882



Historical Plate 9: Aerial Photograph of the Site in 1930 showing the Regent Cinema and the Sheep Market, looking north © Historic England EPW031854



Historical Plate 10: Aerial Photograph of the Site in 1930 showing the Regent Cinema and the Sheep Market, looking east © Historic England EPW031870



Historical Plate 11: Aerial Photograph of the Site in 1947 showing the Regent Cinema and the Sheep Market, looking east © Historic England EAW004498



Historical Plate 12: Aerial Photograph of the Site in 1947 showing the Regent Cinema and the Sheep Market, looking east © Historic England EAW004499

AIR RAID SHELTER





FIG. 3.—SITING OF SINGLE AND DOUBLE SHELTERS IN SHORT GARDENS.

Historical Plate 13: Siting of single (left) and double (right) domestic surface shelters in gardens, from *Directions for the Erection of Domestic Surface Shelters*, May 1939 © The National Archives HO 205/153




Historical Plate 14: Siting of quadruple domestic surface shelter in gardens, from *Directions for the Erection of Domestic Surface Shelters*, May 1939 © The National Archives HO 205/153




Historical Plate 15: Bomb-damaged brick and concrete surface shelter, Camberwell, London, 1941 © The National Archives (HO 186/2244)



Historical Plate 16: Slightly bomb-damaged brick and concrete surface shelter, Camberwell, London, 1941 © The National Archives (HO 186/2244)



Historical Plate 17: Bomb damaged brick and concrete surface shelter at Bellamy's house and stables, Lincoln, showing reinforcing bars in the brickwork, in accordance with Circular 290/40 (Source: Wade 2011: 48)



Historical Plate 18: Research and Experiments Department bomb test of several prototype surface shelters at Richmond Park, London, 19th June 1941 © The National Archives (HO 191/128)



Historical Plate 19: Poor workmanship in brickwork on a surface air raid shelter, showing reinforcing bars (Source: Wade 2011: 40)




Plate 1 Victoria Street site, looking west



Plate 2 Victoria Street site, looking west



Plate 3 Detail of Plate 2 north-south brick wall, looking west



Plate 4 Detail of Plates 2 and 3 north-south brick wall, looking west



Plate 5 Victoria Street site, looking west



Plate 6 Remains of Cistern on Victoria Street site, looking west



Plate 7 Detail of Plate 6 Remains of Cistern on Victoria Street site, looking west



Plate 8 Remains of Cistern on Victoria Street site, looking north



Plate 9 Detail of Plate 8 Remains of Cistern on Victoria Street site, looking north



Plate 10 Victoria Street site, looking west



Plate 11 Manhole of Cistern on Victoria Street Site, looking west



Plate 12 Remains of east-west brick wall on Victoria Street site, looking west



Plate 13 Remains of east-west brick wall on Victoria Street site, looking east



Plate 14 Victoria Street site looking east



Plate 15 Victoria Street site showing Library wall looking east



Plate 16 Victoria Street site looking east