Spalding Common

APPLE TREE

FLOWERING CHERRY TREE

APPLE TREE

DEMOLITION OF EXISTING PAIR OF SEMI-DETACHED TIMBER AND GALVANIZED IRON BUNGALOWS AND ERECTION OF A PAIR OF SEMI-DETACHED REPLACEMENT MODERN BUNGALOWS WITH GARAGES, SOUTH DROVE, (WEST ROAD), SPALDING COMMON, NR. SPALDING, LINCOLNSHIRE.

TF 2120

TF 2219

South Drove Drain

West Road

Fantail Mill Drain

Charinton Farm

BM 9.14

BM 9.28

18·08·93

DETERMINED PLAN

Made and published by the Director General of the Ordnance Survey, Chessington, Surrey, 1968.
Reconstituted from former County Series plans and revised 1967

Antiquities (site of)

Bench Mark

Surface Level

The lines on th
To give a large scale refi