
Surveyed bottom of ditch
Approx' top of ditch - unable to survey due to thick vegetation and trees
Unable to survey area due to thick vegetation and trees
Concrete hardstanding
Existing Greenhouse
Existing Greenhouse
1.8m High Close Boarded Wooden Fence
Garage
Garage
Garage