Key

DENOTES PROPOSED SURFACE WATER EXCEEDANCE ROUTES.

Surveyed bottom of ditch

Approx' top of ditch - unable to survey due to thick vegetation and trees

Unable to survey area due to thick vegetation and trees

Unable to survey area due to thick vegetation and trees

Concrete hardstanding

Existing Greenhouse

Existing Greenhouse

1.8m High Close Boarded Wooden Fence

1.2m High Wall

Concrete hardstanding/drive

Unable to survey area due to thick vegetation and trees

Surveyed bottom of ditch

Surveyed edge of ditch

Surveyed edge of ditch

Unable to survey area due to thick vegetation and trees

Unable to survey area due to thick vegetation and trees

Unable to survey area due to thick vegetation and trees