Online Comment

Application	H18-0313-16
Location	Church Street/Wharf Street Sutton Bridge Spalding PE12 9UF
Proposal	Details submitted relating to landscaping, tree planting, screening and site investigation report. (Conditions 3, 4 and 6 of H18-0842-15).

Name	J Reith
Address	Environmental Health Technician Safety and Environment
Date Submitted	11-05-16
For/Against	Comments

The Site Investigation Report by Ground Engineering (C13771) adequately covers parts i, ii and iii of the contaminated land condition. Remedial works are required on site to deal with contamination issues and therefore I will require evidence of these works in due course (validation report).