Online Comment

Application	H22-0099-24
Location	Land North West of High Road Weston Spalding
Proposal	Details of ground gas verification report (Condition 10 of H22-1249-21)

Name	Sue Armour
Address	Team Leader Environmental Protection SHDC
Date Submitted	02-04-24
For/Against	Comments

I have reviewed the following Geoshield verification repots:
23/07/2022 Ground Gas Verification Report - Plots 2, 3, 4, 5 & 6
03/08/2022 Ground Gas Verification Report - Plots 7, 8, 9, 10, 11, 12 & 13
02/09/2022 Ground Gas Verification Report - Plots 14, 15, 16 & 17
21/09/2022 Ground Gas Verification Report - Plots 18, 19, 20, 21, 22 & 23
04/10/2022 Ground Gas Verification Report - Plots 23 (Integral Garage) & 24
26/10/2022 Ground Gas Verification Report - Plots 25, 26, 27, 28 & 29
01/11/2022 Ground Gas Verification Report - Plots 30 & 31
12/12/2022 Ground Gas Verification Report - Plots 48, 49, 50, 51, 52 & 53
07/02/2023 Ground Gas Verification Report - Plots 32, 33, 42, 43, 44 & 45
24/04/2023 Ground Gas Verification Report - Plots 34, 35, 36, 37, 38 & 39 inclusive
The agreed remediation method statement has been followed and independent verification of the installation of the ground gas protection measures has been undertaken. I therefore have no outstanding concerns regarding plots 2-39, plots 42-46 and plots 28-52 as detailed on the submitted SPAL/WEST/MVP/001 Membrane Validation Plan dated 5/2/24.