Photographic Record of Historic Building

Which is to be demolished

a) Drawing No 2159-P5 indicates the general proportions of the building
b) Photographs

Front elevation indicating orange single clay pantile roof covering over soft red local made stock bricks set in Lime/Ash mortar. Vertical boarded stable and side doors, iron tie bars and 1 no Crittal steel window

Rear elevation indicating facing and roof materials as the front elevation. One number brick up barn door opening (common bricks) 1 no Crittal steel window

South elevation indicating similar brickwork, with high level rectangular framed opening, former vent or window

North elevation indicating similar brickwork, with high level rectangular framed opening, former vent or window

Internal roof looking south indicating the cut roof structure rafter purlins and struts (some grown timber)

Internal looking south indicating proportions of timbers against brickwork and location of Crittal windows

Internal looking north – indication division wall with upper door ro loft and lower door to store. Proportions of crude joinery apparent to loft door

Internal looking upwards/north indicating loft access door and joist ends of loft floor

Internal view from store indicating loft floor joists. Indicating joists from beneath with mid span collars

The structure stands alone and for its age is reasonably upright and water tight.

It has been recommended that where possible materials such as roof tiles and handmade bricks be reclaimed and re-cycled.



Barn front elevation


Barn rear elevation

Barn south elevation



Barn north elevation





Barn internal roof structure looking south


Barn internal looking south

Barn internal looking north




Barn internal loft access


Barn rear window



Barn partially concealed front elevation


Barn internal floor joist to loft