



Plate 9 Stable Block, arched entrance with stable door, looking east



Plate 11 Stable Block, northwestern gable showing door to overhead hay loft, looking south-southwest



Plate 10 Stable Block, example of timber framed and shuttered window, looking northeast



Plate 12 Stable Block, northeastern elevation, showing scarring of removed lean-to structure, looking south